

Tableau de conversion métrique

Pouces en millimètres

POUCES	0	1/16	1/8	3/16	1/4	5/16	3/8	7/16	1/2	9/16	5/8	11/16	3/4	13/16	7/8	15/16
0	0	2	3	5	6	8	10	11	13	14	16	17	19	21	22	24
1	25	27	29	30	32	33	35	37	38	40	41	43	44	46	48	49
2	51	52	54	56	57	59	60	62	64	65	67	68	70	71	73	75
3	76	78	79	81	83	84	86	87	89	90	92	94	95	97	98	100
4	102	103	105	106	108	110	111	113	114	116	117	119	121	122	124	125
5	127	129	130	132	133	135	137	138	140	141	143	144	146	148	149	151
6	152	154	156	157	159	160	162	164	165	167	168	170	171	173	175	176
7	178	179	181	183	184	186	187	189	191	192	194	195	197	198	200	202
8	203	205	206	208	210	211	213	214	216	217	219	221	222	224	225	227
9	229	230	232	233	235	237	238	240	241	243	244	246	248	249	251	252
10	254	256	257	259	260	262	264	265	267	268	270	271	273	274	276	278
11	279	281	283	284	286	287	289	291	292	294	295	297	298	300	302	303
12	305	306	308	310	311	313	314	316	318	319	321	322	324	325	327	329
13	330	331	333	335	337	338	340	341	343	344	346	348	349	351	352	354
14	356	357	359	360	362	364	365	367	368	370	371	373	375	376	378	379
15	381	383	384	386	387	389	391	392	394	395	397	398	400	402	403	405
16	406	408	410	411	413	414	416	418	419	421	422	424	425	427	429	430
17	432	433	435	437	438	440	441	443	445	446	448	449	451	452	454	456
18	457	459	460	462	464	465	467	468	470	471	473	475	476	478	479	481
19	483	484	486	487	489	491	492	494	495	497	498	500	502	503	505	506
20	508	510	511	513	514	516	518	519	521	522	524	525	527	529	530	532